2012-06-07 16:09 DC0547PM13501

8652125642 >>

4237756346 P 116/118 FORM APPROVED

ND PLAI	ENT OF DEFICIENCIES N OF CORRECTION	(X1) PROVIDER/SUPPLIER IDENTIFICATION NUM TN7201	BER:			1 СОМІ	DATE SURVEY COMPLETED R 06/04/2012	
AME OF	PROVIDER OR SUPPLIER				Y, STATE, ZIP CODE		10472012	
	LBROOK SANITARIUN	"	114 CAMPO DAYTON, T	US DRIVE N 37321	<b>3</b>			
(X4) ID PREFIX TAG	REFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL		ULL ION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLE DATE	
T d	This Rule is not met Based on observation the building is constructed the building is constructed the building is constructed to building is constructed to building include;  1. Observation on Marevealed numerous a in patient rooms 24 a patient beds. 2. Observation on Marevealed the metal until the porch area at the missing making the structed in the porch area at the missing making the structed in the front bedow. 3. Observation on Marevealed numerous with the porch area. 4. Observation on Marevealed one (1) broke that the porch area. 5. Observation on Marevealed one (1) broke that the porch area. 6. Observation on Marevealed one (1) broke that the porch area. 6. Observation on Marevealed one (1) broke that the porch area. 6. Observation on Marevealed one (1) broke that the porch area. 6. Observation on Marevealed one (1) broke that the porch area. 6. Observation on Marevealed one (1) broke that the porch area. 6. Observation on Marevealed one (1) broke that the porch area of the porch	shall construct, arrangon of the physical plan nome environment in sety and well-being of the d.  t as evidenced by:  In, the facility failed to a cucted and maintained the residents and staff	assure d to		1) Rooms 24 and 25 repainted on 5/31/12. underpinning has been under porch area at we 5/31/12. Floor tile in replaced on 5/31/12. near front entrance has replaced on 5/30/12.  2) The Maintenance Schecked all rooms on 6 damaged areas to pain repaired/painted any the found.  3) On 5/16/12 the Ma Supervisor will start do Romm/Bath/Equipmer Assessment Form. This be completed on a quant following the Care Plant and Supervisor will start do Romm/Bath/Equipmer Assessment Form. This completed on a quant following the Care Plant	have been Metal n installed est wing exit kitchen area Broken glass s been  Supervisor 6/1/12 for t and hat were  aintenance oing a ht Fall Risk is form will rterly basis n Schedule.  Exhibit # 57 Maintenance a list of room ess to the quarterly	6.5.71	
335} 1:	200-8-608 (5) Buildi	ng Standards	{N 8		Board Quarterly.			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

G6L\$22

TITLE

if continuation sheet 1 of 3

(X6) DATE

2012-06-07 16:09

DC0547PM13501

8652125642 >>

4237756346 P 116/118

FORM APPROVED Division of Health Care Facilities STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING 01 - MAIN BUILDING 01 B. WING TN7201 06/04/2012 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 114 CAMPUS DRIVE LAURELBROOK SANITARIUM **DAYTON, TN 37321** SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) (X4) ID PREFIX PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE (X5) COMPLETE PREFIX TAG CROSS-REFERENCED TO THE APPROPRIATE TAG DATE DEFICIENCY) (N 831) 1200-8-6-.08 (1) Building Standards (N 831) (1) A nursing home shall construct, arrange, and maintain the condition of the physical plant and the overall nursing home environment in such a manner that the safety and well-being of the residents are assured. This Rule is not met as evidenced by: Based on observation, the facility failed to assure the building is constructed and maintained to ensure the safety of the residents and staff. The findings include: 1. Observation on May 14, 2012 at 3:32 p.m. revealed numerous areas of damage to the paint in patient rooms 24 and 25 near the head of the patient beds. 2. Observation on May 14, 2012 at 3:20 p.m. revealed the metal underpinning installed under the porch area at the west exit was damaged or missing making the structure of the building visible from below. Observation on May 14, 2012 at 2:38 p.m. revealed numerous wall and floor tile missing in the kitchen area. 4. Observation on May 14, 2012 at 5:30 p.m. revealed one (1) broken glass panel in the glass partition wall in the front lobby near the front entrance. These findings were verified by the maintenance director and acknowledged by the administrator during the exit conference on May 14, 2012. (N 835) 1200-8-6-,08 (5) Building Standards (N 835) 615/12

TITLE

(X6) DATE

Division of Health Care Facilities

2012-06-07 16:09 DC0547PM13501

8652125642 >> 4237756346 P 117/118

TATEME! NO PLAN	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIEF IDENTIFICATION NUM	R/CLIA (BER:	(X2) MUL A. BUILDI B. WING		100000000	R.	
				DDRESS, CITY, STATE, ZIP CODE			06/04/2012	
AUREL	BROOK SANITARIUN		114 CAMP DAYTON,	US DRIVE				
(X4) ID PREFIX TAG	EFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLE DATE		
	(5) No new nursing home shall be constructed, nor shall major alterations be made to an existing nursing home without prior written approval of the department, and unless in accordance with plans and specifications approved in advance by the department. Before any new nursing home is licensed or before any alteration or expansion of a licensed nursing home can be approved, the applicant must furnish two (2) complete sets of plans and specifications to the department, together with fees and other information as required. Plans and specifications for new construction and major renovations, other than minor alterations not affecting fire and life safety or functional issues, shall be prepared by or under the direction of a licensed architect and/or a licensed engineer and in accordance with the rules of the Board of Architectural and Engineering Examiners.			{N 835}	1) Project was halted on installin HVAC units pending notification by Department of Health on 5/15/12.  2) On 5/28/12 an application was submitted to Mr. Bill Harmon with the Department of Health-plans review division - regarding installation of eight (8) air conditioning units for east wing. Payment of required fee made.  Exhibit # 58		6/5/1	
E p b T C d n rc b th	lans were submitted eginning. he findings include: beservation and interirector on May 14, 2 lew HVAC PTAC united to the seven (7) of installed in the seven land eginstalled in the seven land egins	as evidenced by:  n, the facility failed to a for approval prior to a rview with maintenance 012 at 3:50 p.m. revea t was installed in patie other units are scheduren (7) remaining room for approval from the	e eled a ent		3) The Department's process reviewing plans of any consts was reviewed on 5/28/12 by Healthcare Consultant and as plant changes will be submit Department of Health for apprior to beginning the project 4) Starting 5/31/12 the Main Supervisor will report any reneeding Department of Health approval to the QAPI Command ultimately the Administration will report to the Board Quarter will report to the Board Quarter will report to the Board Quarter will report to the Salva and constant an	ny new ted to proval t		
di	nis finding was verifi rector and acknowle ring the exit confere	ed by the maintenance	ator		ester≜s-contegue deste de servicio. N			